Work Order ID 70307

Thursday, June 02, 2011 2:42:23 PM

Item 1D:

D3508-9

Revision 1D:

Item Name:

Wearplate

Start Date:

6/8/2011

Start Qty: 8.00

Required Date: 6/17/2011

Req'd Qty: 8.00



Accept



Setup Start



Stop

Cust Item ID:

Customer:

Run

Start



Reference:

Approvals:

QC:

Process Plan:

Date: Date: Tooling:

SPC (Y/N):

Date:

Date:

Stop

Sequence ID/ Work Center ID

Operation Description Set Up/ Run Hours Tool ID

Tool # Plan

Accept Qty Code

Reject Qty

Reject Number Stamp

Insp.

Draw Nbr

Revision Nbr

D3508

Rev C

100

FLOW CNC Waterjet

Waterjet

FLOW WATER JET

Memo

1-Cut as per Dwg D3508 □Dwg Rev: Deburr if necessary

0.00

0.00

1311-6-7

1311-6-7

110

OC2- Inspect parts off machine FAI/FAIB

0.00

QC Quality Control

Memo

0.00

120

QC

QC8- Inspect parts - second check

d whole 0.00

Memo

Quality Control

		— - - -								
W/O:			W	ORK ORDER CHAN	GES					
DATE	STEP	PRO	CEDURE CH	ANGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·					-			
										·
						,	· .			
		PAR #:	Fault Cat	egory:	NCR:	Yes N	lo DQ	A :	_ Date: _	·
Re		esolution:	Dispositi	on:	QA: N	/C Clo	sed:		Date: _	
NCR:		1	WORK ORE	DER NON-CONFORM	MANCE (NCR)				· ·
DATE	STEP	Description of NC		ection B		Verific	ation	Approval	Approval	
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
								,	V.	
		<u>.</u> \$ - 1			-					
							,			
							3	2		
							* *			
			. [1	1

Thursday, June 02, 2011 2:42:23 PM

Page 2

Item ID:

D3508-9

Revision ID:

Item Name: Wearplate

Required Date: 6/17/2011

Start Date:

6/8/2011

Start Qty: 8.00 Req'd Oty: 8.00

Accept

Setup Start

Stop

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Qty

Start

Stop

QC:

Date:

SPC (Y/N):

Date:

Sequence ID/ **Work Center ID**

Operation Description Set Up/ **Run Hours**

Tool # Plan

Code

Accept Qty

Reject Reject Number

Insp. Stamp

130

Brake NC

Brake NC

NC BRAKE

Memo

Memo

0.00

0.00

Deburr and form on brake using DT8326 and DT8261as per Dwg D3508

Tool ID

50 1166/03

140

Quality Control

QC5- Inspect part completeness to step on W/O

150

Grey Sandtex(Ref:4.3.5.6) per QSI005 4.3

0.00

0.00

Powdercoat

Powder Coating

15x 8 m./ 11/06/08

M115128

Memo

	-								
W/O:	Programma		W	ORK ORDER CHANGES	3				
DATE	STEP	PROC	EDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
٠									
Part No	*	PAR #:	_ Fault Cat	egory:	NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	_ Dispositi	on:	QA: N/C CI	osed:		Date: _	-
NCR:		W	ORK ORI	DER NON-CONFORMAN	CE (NCR	()			
5.4==	CTED	Description of NC		Corrective Action Section B Initial Action Description			cation	Approval	Approval
DATE	SIEP	STEP Section A		Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
			·		,				
						·			
								- ,	
and the second s									

Work Order ID 70307

Thursday, June 02, 2011 2:42:24 PM

Item ID:

D3508-9

Revision ID:

Item Name:

Wearplate

Start Date:

6/8/2011

QC:

Start Qty: 8.00

Required Date: 6/17/2011

Req'd Qty: 8.00



Accept



Setup Start



Stop

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Run Start

Stop



Sequence ID/

Work Center ID

160

Quality Control

Operation Description

Memo

OC3- Inspect Part Finish

0.00 0.00 Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Qty

Insp. Number Stamp

10 d Il 11/06/09

170

Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

Memo

0.00

180

Quality Control

OC21- Final Inspection - Work Order Release

0.00

0.00

M4(995) MF (1-06-08

	-								
W/O:			WO	RK ORDER CHANG	iES				
DATE	STEP	PRO	OCEDURE CHAN	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						·			
Part No	:	PAR #:	Fault Cated	jory:	_ NCR: Ye	s No DO	A:	Date: _	
	Resolution:							Date: _	
NCR:		•	WORK ORDE	ER NON-CONFORM	ANCE (NO	CR)			•
DATE	STEP	Description of NC		tion B		ication	Approval	Approval	
	STEP Section A		Initial Chief Eng	Action Description Chief Eng	Sigi Da		tion C	Chief Eng	QC Inspector
						-			
		•							·
_									

Picklist Print

Thursday, June 02, 2011 2:42:20 PM

Work Order ID: 70307

Parent Item:

D3508-9

Parent Item Name: Wearplate

Component Item ID/



Start Date: 6/8/2011

Required Date: 6/17/2011

Start Qty: 8.00

Required Qty: 8.00

Comments:

Item Name

M304S20GA

IPP Rev:A New Issue 07.06.12

EC IPP Rev:B Rev C dwg 07-12-06 DD

Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
 	Purchased	No	4 **	*	100	sf	10.3814	0.417	3.511579	٤	H.	
									T B	11-6	-7	

304/316 .040 Sheet

<u>Location</u>	Loc Qty	Loc Code		
MAT020	10.3814		***************************************	6
116623	0.2			(10
117550	10.1814		117993	
117993				


W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	CEDURE CH	IANGE		Post v	Ву	Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				,								
		·			•							
Part No	:	PAR #:	Fault Ca	tegory:		_ NCF	R: Yes I	No DQA: _	Date: _			
	. R	lesolution:	Disposit	ion:	•	_ QA:	N/C Clo	sed:	Date: _			
NCR:		V	VORK OR	DER NON-C	ONFORMA	NCE	(NCR))				
DATE	STEP	Description of NC	Corrective Action Section			on B		Verification	on Approval	Approval		
DATE	SIEP	Section A	Initial Chief Eng	Action	Description Chief Eng		Sign & Date	Section C		QC Inspector		
	,	·										
					300000							
	-	,				ALL PROPERTY OF THE PARTY OF TH						
•												
			- 00	,								
		,										

DART AEROSPACE LTD	Work Order:	10501
Description: Wearplate	Part Number:	D3508-9
Inspection Dwg: D3508 Rev: C		Page 1 of 1


	11101	ARTICLE INSP	ECHON	CHECKI	-101		
	X	First Article		Prototyp	е		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	C	omments
2.063	+/-0.010	9.069	×		U BOZ		
2.813	+/-0.010	2.80	x		V		
0.375	+/-0.010	373	>		V		
2.90	+/-0.030	7.904	מ		V		***
5.800	+/-0.010	5,800	2		TOOL		
11.600	+/-0.010	11.600	·		7		
17.400	+/-0.010	7.400	8		7		
Ø0.188	+0.005/-0.001	ાંવડ	>		7		
0.300	+/-0.010	308	20		Ù		
0.300	+/-0.010	.303	y		V		
0.038	+/-0.010	,034	7		V		
Measured by: Date:	B (1-6-7	Audited by: S	o6/08	Pro	totype Approv	le:	N/A N/A

Rev	Date	Change	Revised by	Approved
Α	08.07.24	New Issue	KJ/DD SX	177

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
<u> </u>													
Part No		PAR #:	Fault Cateç	gory:	NCR: Yes No DQA: Date:								
	R	lesolution:	Disposition	n:	QA:	N/C Clo	sed:		Date:				
NCR:	-		WORK ORDE	R NON-CONFORM	JANCE	(NCR)							
DATE	STEP	Description of NC	Corrective Action Section B				Verifica	ation	Approval	Approval			
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Section	n C	Chief Eng	QC Inspector			



	1												
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
							,						
					·					***************************************			
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Y	es N	o DQ	A:	_ Date: _				
	Re	esolution:	Dispositio	n:	_ QA: N/0	Clos	sed:		Date: _				
NCR:		·	WORK ORD	ER NON-CONFORM	ANCE (N	CR)							
DATE	STEP	Description of NC			ection B n Sign &			ation	Approval	Approval			
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng		ate	Secti	on C	Chief Eng	QC Inspector			
•										-			
•		-								-			



Dail AC	ospace	s Liu									
W/O:			W	ORK ORD	ER CHAN	IGES					1
DATE	STEP	PRO	CEDURE CH	ANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•									
								·			;
Part No		PAR #:	Fault Cat	egory:		NCF	R: Yes	No DQ	A:	Date:	
Resolution:			Dispositi	on:		QA:	N/C Cld	sed:		Date: _	
NCR:		· V	ORK ORE	DER NON-	CONFORI	MANCE	(NCR)			
	0777	Description of NC	Corrective Action S			ection B		Verification		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng		Descriptio Chief Eng	n	Sign & Date		tion C	Chief Eng	QC Inspector
											n ugy
											2 San
		·			•				•		